

Date : 03/05/2026
 Project No : 2025C214
 Client Company : Artisan
 Arrival Time : 03/05/2026 07:30
 Onsite Hours : 03:00

ASEC Report ID : 91079
 Name of the Project : NW Unit 4 BRIDGE (Materials Testing)
 Project Location : Dallas
 Weather : sunny
 Departure Time : 03/05/2026 10:30
 ASEC Technician Name : Clyde Smith

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

Our representative was on site to observe the blast contractor drill test holes for the north side bridge embankment (east side) at sheet piling. The contractor performed a total of seven (7) test drill holes, five feet off the east side face of sheet piles starting at the bend. The holes were drilled five feet apart to the first twenty feet then ten feet apart to forty feet with the last hole at five feet to the end of sheet piling. See attached drill log for results.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.

Advanced Explosives Test Drill Log


Job Name: _____ Date: 03/05/26
 Customer: _____ Driller: Pedro

Hole	Location	Cut	Hit Rock	Stopped Drill	Comments
1		2.5	3.9	23.5	
2		2.5	3	20	58-9.4
3		1.5	9.9	10	
4		2.5	4.4	20	58-9.9 V-R-12.5
5		2.5	3.8	20	58-9-11
6		2.5	4.3	20	V-7.1-7.6
7		2.5	4	20	



Date : 03/05/2026
Project No : 2025C214
Client Company : Artisan
Arrival Time : 03/05/2026 07:30
Onsite Hours : 03:00

ASEC Report ID : 91079
Name of the Project : NW Unit 4 BRIDGE (Materials Testing)
Project Location : Dallas
Weather : sunny
Departure Time : 03/05/2026 10:30
ASEC Technician Name : Clyde Smith



Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.