

Date : 08/09/2025
Project No : 2023C180
Client Company : Artisan Communities
Arrival Time : 08/09/2025 07:00
Onsite Hours : 00:30

ASEC Report ID : 84115
Name of the Project : Lakeside Sub., Lovers Lane > Retaining
Wall
Project Location : Calhoun
Weather : overcast
Departure Time : 08/09/2025 07:30
ASEC Technician Name : Sean Willett


As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

On the above date, the technician was onsite as requested by the contractor for observation/testing of soil.

Upon arrival to the site, it appeared the site was over saturated from previous rainfall. The contractor requested a moisture check. Moisture checks were found to be well above optimum moisture contents. The technician provided a copy of test results to the contractor.

The retaining wall appears to have approximate 2 feet of fill left to be at finished grade.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Date : 08/09/2025
Project No : 2023C180
Client Company : Artisan Communities
Arrival Time : 08/09/2025 07:00
Onsite Hours : 00:30

ASEC Report ID : 84115
Name of the Project : Lakeside Sub., Lovers Lane > Retaining
Wall
Project Location : Calhoun
Weather : overcast
Departure Time : 08/09/2025 07:30
ASEC Technician Name : Sean Willett



Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.