

Date : 07/18/2025
Project No : 2024C217
Client Company : Artisan
Arrival Time : 07/18/2025 08:00
Onsite Hours : 03:00

ASEC Report ID : 83179
Name of the Project : Naturewalk - 7 Hills Amenities
Project Location : Dallas
Weather : Mostly sunny
Departure Time : 07/18/2025 11:00
ASEC Technician Name : Safiullah Momand

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

Ongoing activities included:

1. GAB placement on Shaelly Road (right side).
2. Proof-rolling work over the patches and subgrade soils on Shaelly Road (left side).

Observation and recommendations:

The proof-rolling was observed jointly with Paulding County representative, GAB contractor and ASEC personnel. Proof-roll results show no visible pumping and/or rutting.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Date : 07/18/2025
Project No : 2024C217
Client Company : Artisan
Arrival Time : 07/18/2025 08:00
Onsite Hours : 03:00

ASEC Report ID : 83179
Name of the Project : Naturewalk - 7 Hills Amenities
Project Location : Dallas
Weather : Mostly sunny
Departure Time : 07/18/2025 11:00
ASEC Technician Name : Safiullah Momand



4 inches pitches repair of Subgrade



4 inches pitches repair of Subgrade



4 inches pitches repair of Subgrade



Proof rolling

Date : 07/18/2025
Project No : 2024C217
Client Company : Artisan
Arrival Time : 07/18/2025 08:00
Onsite Hours : 03:00

ASEC Report ID : 83179
Name of the Project : Naturewalk - 7 Hills Amenities
Project Location : Dallas
Weather : Mostly sunny
Departure Time : 07/18/2025 11:00
ASEC Technician Name : Safiullah Momand




Proof rolling



GAB work in progress



West Deceleration Lane GAB work



West Deceleration Lane GAB work

Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.