

Daily Field Report

 $\label{eq:ASEC} ASEC \; Report \; ID: 85316 \\ Name \; of the \; Project: Nature walk - 7 \; Hills \; Amenities$

Project Location : Dallas Weather : Sunny

Departure Time: 09/09/2025 16:00 ASEC Technician Name: Clyde Smith

Date: 09/09/2025 Project No: 2024C217 Client Company: Artisan Arrival Time: 09/09/2025 08:00

Onsite Hours: 08:00

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

On the above date our representative was on site and observed the contractor continue subgrade repairs after removing an area that had failed asphalt at Azalea Crossing. The first repair area #1 was observed by removing in place base GAB averaging 4.5″ and 5.0″ at observed areas performing hand auger borings to depths of minus three feet. The in-place subgrade soils were probed using a rounded end steel rod indicating slightly above optimum moisture soils in place. It was recommended to clip these in-place subgrade soils -6″ and replace with additional GAB stone to increase base stone thicknesses to 10″ to 12″. The area observed was approximately 9′x 175′ between house addresses 295 and 331. The writer observed GAB stone replacement, but compaction efforts weren't completed and will be re-observed on 9/10/25. See attached photos below.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Spreading subbase stone



Hand auger boring and probing



Daily Field Report

 $\begin{array}{c} {\rm ASEC\ Report\ ID:85316} \\ {\rm Name\ of\ the\ Project:Naturewalk-7\ Hills\ Amenities} \\ {\rm Project\ Location:Dallas} \end{array}$

oject Location : Dallas Weather : Sunny

Departure Time: 09/09/2025 16:00 ASEC Technician Name: Clyde Smith

Date: 09/09/2025 Project No: 2024C217 Client Company: Artisan Arrival Time: 09/09/2025 08:00 Onsite Hours: 08:00



Clipping recommended sub grade



Replacing subbase stone



Wetting and compacting subbase stone



Practice test roll with small truck



Daily Field Report

Date: 09/09/2025 Project No: 2024C217 Client Company: Artisan Arrival Time: 09/09/2025 08:00

Onsite Hours: 08:00

ASEC Report ID : 85316 Name of the Project : Naturewalk - 7 Hills Amenities Project Location : Dallas

Weather: Sunny

Departure Time: 09/09/2025 16:00 ASEC Technician Name: Clyde Smith



Perform hand auger boring and probe sub grade

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consultiing LLC.