

Date : 02/21/2025
Project No : 2024C296
Client Company : Artisan
Arrival Time : 02/21/2025 14:00
Onsite Hours : 02:00

ASEC Report ID : 77815
Name of the Project : Heritage Pointe - Footing Inspections
Project Location : Villa Rica
Weather : sunny
Departure Time : 02/21/2025 16:00
ASEC Technician Name : Vamsi Polisetty

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

Heritage Pointe Villa Rica: Footings Inspection (Lot #66)


After conducting the Dynamic Cone Penetrometer (DCP) test on both sides of Lot #66, small stones and rocks were found in the soil. A 4-foot trench excavation was performed, and during the inspection, traces of organic material were discovered below a depth of 2 feet.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Date : 02/21/2025
Project No : 2024C296
Client Company : Artisan
Arrival Time : 02/21/2025 14:00
Onsite Hours : 02:00

ASEC Report ID : 77815
Name of the Project : Heritage Pointe - Footing Inspections
Project Location : Villa Rica
Weather : sunny
Departure Time : 02/21/2025 16:00
ASEC Technician Name : Vamsi Polisetty



Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.