

Date : 03/28/2026
Project No : 2024C296
Client Company : Artisan
Arrival Time : 03/28/2026 08:00
Onsite Hours : 01:00


ASEC Report ID : 91757
Name of the Project : Heritage Pointe - Footing Inspections
Project Location : Villa Rica
Weather : Sunny
Departure Time : 03/28/2026 09:00
ASEC Technician Name : Sean Willett

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

Our ASEC representative was on site to observe the contractor and for the observation/testing of the placement of fill/backfill.

A site inspection of Lot #109 was performed. It appears the contractor has placed soil lifts to final grade. Density testing was performed and recorded, as there were no contractors on site to report test results to. The filled area visually appears to be well compacted and stable.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.