

Date : 04/21/2025
Project No : 2025C150
Client Company : Davidson Homes
Arrival Time : 04/21/2025 07:30
Onsite Hours : 10:00

ASEC Report ID : 80406
Name of the Project : Riverwood Retaining Wall
Project Location : Dallas
Weather : Partly cloudy
Departure Time : 04/21/2025 17:30
ASEC Technician Name : Vamsi Polisetty

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

Following up on the progress from the previous day, work has continued behind Lots #224-#229. The contractor has made progress in the preparation of the retaining wall foundation.

Focusing on backfilling and compaction operations behind the newly installing retaining wall structure along Lots #224-3229, Following the drainage installation, the next layer of backfill was placed over the previously installed geogrid reinforcement sheet, in preparation for subsequent compaction. Excavation and placement of fill material was conducted using a Kobelco 310LC excavator and transported on site with a CAT 750 dump truck. Subsequent to placement, two Takeuchi TL12R2 Bobcats were used to distribute the fill uniformly along Lots #224-3229. Once the fill was evenly spread, compaction was carried out using a Bomag BW211 sheep foot compactor roller.

Nuclear gauge density testing was conducted on the compacted layer to evaluate moisture content and dry density. Based on this data, the superintendent was advised to dedicate additional time to compaction in areas with insufficient density. After re-compaction, general probing and proof-rolling tests were performed.

Upon successful compaction of the first lift, the contractor advanced to the next layer of backfill. This subsequent layer underwent the same testing and quality control process. Near the wall the compaction is carried out with remote compactor BMP8500 for even compaction along the retaining wall.

Following backfills operations, preparations commenced for the next course of retaining wall construction, including Geo Grid Reinforcement sheet placement and layout for the upcoming lift.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.

Date : 04/21/2025
Project No : 2025C150
Client Company : Davidson Homes
Arrival Time : 04/21/2025 07:30
Onsite Hours : 10:00

ASEC Report ID : 80406
Name of the Project : Riverwood Retaining Wall
Project Location : Dallas
Weather : Partly cloudy
Departure Time : 04/21/2025 17:30
ASEC Technician Name : Vamsi Polisetty



Date : 04/21/2025
Project No : 2025C150
Client Company : Davidson Homes
Arrival Time : 04/21/2025 07:30
Onsite Hours : 10:00

ASEC Report ID : 80406
Name of the Project : Riverwood Retaining Wall
Project Location : Dallas
Weather : Partly cloudy
Departure Time : 04/21/2025 17:30
ASEC Technician Name : Vamsi Polisetty



Date : 04/21/2025
Project No : 2025C150
Client Company : Davidson Homes
Arrival Time : 04/21/2025 07:30
Onsite Hours : 10:00

ASEC Report ID : 80406
Name of the Project : Riverwood Retaining Wall
Project Location : Dallas
Weather : Partly cloudy
Departure Time : 04/21/2025 17:30
ASEC Technician Name : Vamsi Polisetty



Date : 04/21/2025
Project No : 2025C150
Client Company : Davidson Homes
Arrival Time : 04/21/2025 07:30
Onsite Hours : 10:00

ASEC Report ID : 80406
Name of the Project : Riverwood Retaining Wall
Project Location : Dallas
Weather : Partly cloudy
Departure Time : 04/21/2025 17:30
ASEC Technician Name : Vamsi Polisetty




Date : 04/21/2025
Project No : 2025C150
Client Company : Davidson Homes
Arrival Time : 04/21/2025 07:30
Onsite Hours : 10:00

ASEC Report ID : 80406
Name of the Project : Riverwood Retaining Wall
Project Location : Dallas
Weather : Partly cloudy
Departure Time : 04/21/2025 17:30
ASEC Technician Name : Vamsi Polisetty



Date : 04/21/2025
Project No : 2025C150
Client Company : Davidson Homes
Arrival Time : 04/21/2025 07:30
Onsite Hours : 10:00

ASEC Report ID : 80406
Name of the Project : Riverwood Retaining Wall
Project Location : Dallas
Weather : Partly cloudy
Departure Time : 04/21/2025 17:30
ASEC Technician Name : Vamsi Polisetty



Date : 04/21/2025
Project No : 2025C150
Client Company : Davidson Homes
Arrival Time : 04/21/2025 07:30
Onsite Hours : 10:00

ASEC Report ID : 80406
Name of the Project : Riverwood Retaining Wall
Project Location : Dallas
Weather : Partly cloudy
Departure Time : 04/21/2025 17:30
ASEC Technician Name : Vamsi Polisetty




Date : 04/21/2025
Project No : 2025C150
Client Company : Davidson Homes
Arrival Time : 04/21/2025 07:30
Onsite Hours : 10:00

ASEC Report ID : 80406
Name of the Project : Riverwood Retaining Wall
Project Location : Dallas
Weather : Partly cloudy
Departure Time : 04/21/2025 17:30
ASEC Technician Name : Vamsi Polisetty



Date : 04/21/2025
Project No : 2025C150
Client Company : Davidson Homes
Arrival Time : 04/21/2025 07:30
Onsite Hours : 10:00

ASEC Report ID : 80406
Name of the Project : Riverwood Retaining Wall
Project Location : Dallas
Weather : Partly cloudy
Departure Time : 04/21/2025 17:30
ASEC Technician Name : Vamsi Polisetty




Date : 04/21/2025
Project No : 2025C150
Client Company : Davidson Homes
Arrival Time : 04/21/2025 07:30
Onsite Hours : 10:00

ASEC Report ID : 80406
Name of the Project : Riverwood Retaining Wall
Project Location : Dallas
Weather : Partly cloudy
Departure Time : 04/21/2025 17:30
ASEC Technician Name : Vamsi Polisetty




Date : 04/21/2025
Project No : 2025C150
Client Company : Davidson Homes
Arrival Time : 04/21/2025 07:30
Onsite Hours : 10:00

ASEC Report ID : 80406
Name of the Project : Riverwood Retaining Wall
Project Location : Dallas
Weather : Partly cloudy
Departure Time : 04/21/2025 17:30
ASEC Technician Name : Vamsi Polisetty



Date : 04/21/2025
Project No : 2025C150
Client Company : Davidson Homes
Arrival Time : 04/21/2025 07:30
Onsite Hours : 10:00

ASEC Report ID : 80406
Name of the Project : Riverwood Retaining Wall
Project Location : Dallas
Weather : Partly cloudy
Departure Time : 04/21/2025 17:30
ASEC Technician Name : Vamsi Polisetty



Date : 04/21/2025
Project No : 2025C150
Client Company : Davidson Homes
Arrival Time : 04/21/2025 07:30
Onsite Hours : 10:00

ASEC Report ID : 80406
Name of the Project : Riverwood Retaining Wall
Project Location : Dallas
Weather : Partly cloudy
Departure Time : 04/21/2025 17:30
ASEC Technician Name : Vamsi Polisetty



Date : 04/21/2025
Project No : 2025C150
Client Company : Davidson Homes
Arrival Time : 04/21/2025 07:30
Onsite Hours : 10:00

ASEC Report ID : 80406
Name of the Project : Riverwood Retaining Wall
Project Location : Dallas
Weather : Partly cloudy
Departure Time : 04/21/2025 17:30
ASEC Technician Name : Vamsi Polisetty



Date : 04/21/2025
Project No : 2025C150
Client Company : Davidson Homes
Arrival Time : 04/21/2025 07:30
Onsite Hours : 10:00

ASEC Report ID : 80406
Name of the Project : Riverwood Retaining Wall
Project Location : Dallas
Weather : Partly cloudy
Departure Time : 04/21/2025 17:30
ASEC Technician Name : Vamsi Polisetty



Date : 04/21/2025
Project No : 2025C150
Client Company : Davidson Homes
Arrival Time : 04/21/2025 07:30
Onsite Hours : 10:00

ASEC Report ID : 80406
Name of the Project : Riverwood Retaining Wall
Project Location : Dallas
Weather : Partly cloudy
Departure Time : 04/21/2025 17:30
ASEC Technician Name : Vamsi Polisetty



ASEC Report ID : 80406
Name of the Project : Riverwood Retaining Wall
Project Location : Dallas
Weather : Partly cloudy
Departure Time : 04/21/2025 17:30
ASEC Technician Name : Vamsi Polisetty

Date : 04/21/2025
Project No : 2025C150
Client Company : Davidson Homes
Arrival Time : 04/21/2025 07:30
Onsite Hours : 10:00



Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.