

Date : 04/03/2025
Project No : 2025C160
Client Company : Artisan
Arrival Time : 04/03/2025 4:00
Onsite Hours : 02:00

ASEC Report ID : 79431
Name of the Project : Rockmart Township - 115 Felton Drive
Project Location : Rockmart
Weather : Sunny
Departure Time : 04/03/2025 6:00
ASEC Technician Name : Clyde Smith

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

On the above date our representative was on site as requested to observe the grading contractor (Wilbanks) strip existing subgrade soils from Lot #33, removing organic topsoil. The writer visually inspected the subgrade by proof-rolling, using a loaded off-road dump truck making two passes over all areas of concern. Subgrade soils appeared stable under traffic with no apparent pumping or deflection and was suitable for fill placement.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Date : 04/03/2025
Project No : 2025C160
Client Company : Artisan
Arrival Time : 04/03/2025 4:00
Onsite Hours : 02:00

ASEC Report ID : 79431
Name of the Project : Rockmart Township - 115 Felton Drive
Project Location : Rockmart
Weather : Sunny
Departure Time : 04/03/2025 6:00
ASEC Technician Name : Clyde Smith



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.