

Date : 04/24/2026  
Project No : 2025C214  
Client Company : Artisan  
Arrival Time : 04/24/2026 07:30  
Onsite Hours : 03:00

ASEC Report ID : 93455  
Name of the Project : NW Unit 4 BRIDGE (Materials Testing)  
Project Location : Dallas  
Weather : Sunny  
Departure Time : 04/24/2026 10:30  
ASEC Technician Name : Clyde Smith

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

On the above date our representative was onsite to observe the excavated subgrade for the east side radius roundabout (north side of the bridge). The subgrade soils were observed by probing using a rounded end steel rod and appeared stable which was suitable for base stone placement. The observation was also observed by Thompson Grading and a Paulding County official.

The writer assisted in observing concrete placement and testing at the north side bridge first wall pour.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Performing slump test during concrete pour at north side bridge wall pour



Observing form work prior to concrete pour

Date : 04/24/2026  
Project No : 2025C214  
Client Company : Artisan  
Arrival Time : 04/24/2026 07:30  
Onsite Hours : 03:00

ASEC Report ID : 93455  
Name of the Project : NW Unit 4 BRIDGE (Materials Testing)  
Project Location : Dallas  
Weather : Sunny  
Departure Time : 04/24/2026 10:30  
ASEC Technician Name : Clyde Smith



Observing subgrade at east side radius round about to bridge with Thompson Grading and Paulding Co. official using a rounded end steel rod.



*Kenneth Mosman*

**Kenneth Mosman**

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.