

Date : 02/10/2026  
Project No : 2026C103  
Client Company : Artisan  
Arrival Time : 02/10/2026 14:30  
Onsite Hours : 03:00

ASEC Report ID : 90210  
Name of the Project : NW PH 2, UNIT 4  
Project Location : Dallas  
Weather : sunny  
Departure Time : 02/10/2026 17:30  
ASEC Technician Name : Clyde Smith

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

On the above date our representative was on site to observe backfilling of the 48" RCP storm line between the OCS and headwall#3 at Unit 4 phase 2 water quality pond, performing density tests using a Troxler Nuclear gauge model 3430, serial no. 91643. The writer observed the anti-seep collars in place prior to backfilling which appeared to be in compliance with site documents. Compaction results were in compliance with job specifications.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Performing density tests at 48 " rcp storm line between OCS and headwall #3



Date : 02/10/2026  
Project No : 2026C103  
Client Company : Artisan  
Arrival Time : 02/10/2026 14:30  
Onsite Hours : 03:00

ASEC Report ID : 90210  
Name of the Project : NW PH 2, UNIT 4  
Project Location : Dallas  
Weather : sunny  
Departure Time : 02/10/2026 17:30  
ASEC Technician Name : Clyde Smith



*Kenneth Mosman*

**Kenneth Mosman**

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.