

Date : 05/09/2025  
Project No : 2024C213  
Client Company : WDG  
Arrival Time : 05/09/2025 8:30  
Onsite Hours : 10:00

ASEC Report ID : 81582  
Name of the Project : Covington Town Center PH II  
Project Location : Covington, GA  
Weather : sunny  
Departure Time : 05/09/2025 18:30  
ASEC Technician Name : Aminullah Azimi

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

Our ASEC representative arrived on site to observe the placement of MSE retaining walls A and B.

It was noted that the base course was backfill behind the block and in the cells with No. 57 stone.

Every 2<sup>nd</sup> course a geotextile fabric was placed followed by an 8-inch compacted lift.

No. 57 stone was utilized 1-foot behind the block and within the cells.

No remedial recommendation was made.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Date : 05/09/2025  
Project No : 2024C213  
Client Company : WDG  
Arrival Time : 05/09/2025 8:30  
Onsite Hours : 10:00

ASEC Report ID : 81582  
Name of the Project : Covington Town Center PH II  
Project Location : Covington, GA  
Weather : sunny  
Departure Time : 05/09/2025 18:30  
ASEC Technician Name : Aminullah Azimi



Date : 05/09/2025  
Project No : 2024C213  
Client Company : WDG  
Arrival Time : 05/09/2025 8:30  
Onsite Hours : 10:00

ASEC Report ID : 81582  
Name of the Project : Covington Town Center PH II  
Project Location : Covington, GA  
Weather : sunny  
Departure Time : 05/09/2025 18:30  
ASEC Technician Name : Aminullah Azimi



*Kenneth Mosman*

**Kenneth Mosman**

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.