

Date : 12/11/2024
Project No : 2023C159
Client Company : CW Matthews
Arrival Time : 12/11/2024 08:00
Onsite Hours : 04:00


ASEC Report ID : 74282
Name of the Project : Airfield Repairs 2021-23
Project Location : HJAlA, Atlanta, GA
Weather : cloudy
Departure Time : 12/11/2024 12:00
ASEC Technician Name : Vamsi Polisetty

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

Airfield Repairs:

- A topsoil sample was collected from the topsoil stockpile located at the Luck Stone Quarry in Atlanta for soil testing for suitability to be used on this project.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Date : 12/11/2024
Project No : 2023C159
Client Company : CW Matthews
Arrival Time : 12/11/2024 08:00
Onsite Hours : 04:00

ASEC Report ID : 74282
Name of the Project : Airfield Repairs 2021-23
Project Location : HJAJA, Atlanta, GA
Weather : cloudy
Departure Time : 12/11/2024 12:00
ASEC Technician Name : Vamsi Polisetty



Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.