

Date : 06/17/2025
Project No : 2023C159
Client Company : CW Matthews
Arrival Time : 06/16/2025 21:45
Onsite Hours : 10:15

ASEC Report ID : 82266
Name of the Project : Airfield Repairs 2021-23
Project Location : HJAlA, Atlanta, GA
Weather :
Departure Time : 06/17/2025 08:00
ASEC Technician Name : Solomon Cherie

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

The spalls were identified and marked for cracked concrete which was removed using various hand tools and machine.


After the concrete was broken up, the space was prepared readied for concrete pouring.

One (1) set of four (4) beams was cast. A set of previously cast beams were transported to the CWM laboratory.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Picture showing the identified and marked spall



Spall being field by a concrete

Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.