

Date : 09/12/2024  
Project No : 2023C180  
Client Company : Artisan Communities  
Arrival Time : 09/05/2024 08:00  
Onsite Hours : 9:00

ASEC Report ID : 69531  
Name of the Project : Lakeside Sub. - Lovers Lane, Calhoun  
Project Location : Calhoun  
Weather : Partly cloudy  
Departure Time : 09/05/2024 17:00  
ASEC Technician Name : Solomon Cherie

---

Our AS Engineering & Consulting (ASEC) representative arrived on site to observe field activities. The following tasks were performed:

Backfilling of the storm line (b/n BB 9-11) and sewer lines (b/n 10.1 & 10.3) continued today. Density test results are attached in a separate report.

Backfilling of the next lift was completed but not compacted yet. Compaction and density testing will be tomorrow.

Please contact us if you have any questions regarding this report or the density test results for today.



Storm line a BB9-BB11



Nuclear gauge tests at sewer line 10.1-1.3

Date : 09/12/2024  
Project No : 2023C180  
Client Company : Artisan Communities  
Arrival Time : 09/05/2024 08:00  
Onsite Hours : 9:00

ASEC Report ID : 69531  
Name of the Project : Lakeside Sub. - Lovers Lane, Calhoun  
Project Location : Calhoun  
Weather : Partly cloudy  
Departure Time : 09/05/2024 17:00  
ASEC Technician Name : Solomon Cherie



Compacted sewer line

*Kenneth Mosman*

**Kenneth Mosman**

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.