

Date : 09/19/2024
Project No : 2023C180
Client Company : Artisan Communities
Arrival Time : 09/19/2024 08:00
Onsite Hours : 9:00

ASEC Report ID : 70292
Name of the Project : Lakeside Sub. - Lovers Lane, Calhoun
Project Location : Calhoun
Weather : Partly cloudy
Departure Time : 09/19/2024 17:00
ASEC Technician Name : Solomon Cherie

Our AS Engineering & Consulting (ASEC) representative arrived on site to observe field activities. The following tasks were performed:

Backfilling of the storm line AI-9 to AI-10 and sewer lines BH2 to BH3 continued today. Compaction equipment suffered a breakdown during lift placement and will be continued tomorrow.

Please contact us if you have any questions regarding this report.



Storm line b/n manhole AI-9 to AI-10.



Sewer line b/n manhole b/n BH 2 and BH3

Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.