

Date : 09/16/2024  
Project No : 2023C180  
Client Company : Artisan Communities  
Arrival Time : 09/16/2024 08:30  
Onsite Hours : 08:45

ASEC Report ID : 70000  
Name of the Project : Lakeside Sub. - Lovers Lane, Calhoun  
Project Location : Calhoun  
Weather :  
Departure Time : 09/16/2024 17:15  
ASEC Technician Name : Solomon Cherie

---

Our AS Engineering & Consulting (ASEC) representative arrived on site to observe field activities. The following tasks were performed:

Backfilling of the storm line (b/n BB 9-10) and pipe placement for (BB9-BH1-BH2) and sewer lines (b/n 10.2 & 10.3) continued today. Density test results are attached in a separate report.

Thirty-two (32) holes were drilled in rock today in preparations for blasting tomorrow (for both the building pad and roadway).

Please contact us if you have any questions regarding this report or the density test results for today.



Storm line BH1-BH2



After blasting

Date : 09/16/2024  
Project No : 2023C180  
Client Company : Artisan Communities  
Arrival Time : 09/16/2024 08:30  
Onsite Hours : 08:45

ASEC Report ID : 70000  
Name of the Project : Lakeside Sub. - Lovers Lane, Calhoun  
Project Location : Calhoun  
Weather :  
Departure Time : 09/16/2024 17:15  
ASEC Technician Name : Solomon Cherie



Storm line BB9-BB10



Workers preparing to blast

*Kenneth Mosman*

**Kenneth Mosman**

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.