



Date : 11/21/2024  
Project No : 2024C168  
Client Company : CCG  
Arrival Time : 11/21/2024 12:30  
Onsite Hours : 03:30

ASEC Report ID : 73514  
Name of the Project : Reserve @ Gum Springs  
Project Location : Jefferson  
Weather : cloudy  
Departure Time : 11/21/2024 16:00  
ASEC Technician Name : Aminullah Azimi

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

- The work was planned for the water line in front of Lots #89 through #100 and Lots #179 through #181 this day.
- Since there was rain the day before, the contractor did not backfill due to the wet materials.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Date : 11/21/2024  
Project No : 2024C168  
Client Company : CCG  
Arrival Time : 11/21/2024 12:30  
Onsite Hours : 03:30

ASEC Report ID : 73514  
Name of the Project : Reserve @ Gum Springs  
Project Location : Jefferson  
Weather : cloudy  
Departure Time : 11/21/2024 16:00  
ASEC Technician Name : Aminullah Azimi



*Kenneth Mosman*

**Kenneth Mosman**

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.