

Date : 11/22/2024
Project No : 2024C168
Client Company : CCG
Arrival Time : 11/22/2024 10:30
Onsite Hours : 04:00

ASEC Report ID : 73523
Name of the Project : Reserve @ Gum Springs
Project Location : Jefferson
Weather : sunny
Departure Time : 11/22/2024 14:30
ASEC Technician Name : Aminullah Azimi

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

- Work was planned for water line in front of Lots# 24 through #126 and Lots #178 through #180 along with stabilization of the retaining wall footing using riprap at the creek crossing this day.
- Since there was rain the day before, the contractor did not backfill due to the wet materials.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Date : 11/22/2024
Project No : 2024C168
Client Company : CCG
Arrival Time : 11/22/2024 10:30
Onsite Hours : 04:00

ASEC Report ID : 73523
Name of the Project : Reserve @ Gum Springs
Project Location : Jefferson
Weather : sunny
Departure Time : 11/22/2024 14:30
ASEC Technician Name : Aminullah Azimi



Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.