




Date : 02/04/2025
Project No : 2024C168
Client Company : Century Communities
Arrival Time : 02/04/2025 13:30
Onsite Hours : 04:30

ASEC Report ID : 77309
Name of the Project : Reserve @ Gum Springs
Project Location : Jefferson, Jackson County, Georgia
Weather : sunny
Departure Time : 02/04/2025 18:00
ASEC Technician Name : Aminullah Azimi

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

- The placement and compaction of backfill soils for the sewer trench, between MHS A5 to MHS A6, continued this day.
- Density testing was not performed this day due to the area not being ready yet.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Date : 02/04/2025
Project No : 2024C168
Client Company : Century Communities
Arrival Time : 02/04/2025 13:30
Onsite Hours : 04:30

ASEC Report ID : 77309
Name of the Project : Reserve @ Gum Springs
Project Location : Jefferson, Jackson County, Georgia
Weather : sunny
Departure Time : 02/04/2025 18:00
ASEC Technician Name : Aminullah Azimi



Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.