

Date : 09/05/2025
Project No : 2024C195
Client Company : CWM
Arrival Time : 09/04/2025 22:30
Onsite Hours : 9:00

ASEC Report ID : 85920

Name of the Project : Ramp 21 Replacement

Project Location : HJALA

Weather : Clear

Departure Time : 09/05/2025 07:30

ASEC Technician Name : Austin Coleman

Test Date	Test Number	Moisture Content (%)	Dry Density (pcf)	Proctor Number	Max. Dry Density (pcf)	Optimum Moisture (%)	Compaction (%)	Specified Compaction (%)	ASTM Test Method	Pass/Fail
09/05/2025	1	2.7	132.3	Proctor #1	134.9	8.7	98.1	98	D6938	Pass
Location : Ramp 33 sinkhole repair, Elv/Depth :3 feet below finished grade Comment : Tested By : Austin Coleman Gauge Serial No. : 29588										

Remark: Test performed in general accordance with signed referenced ASTM Method.



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.

Date : 09/05/2025
Project No : 2024C195
Client Company : CWM
Arrival Time : 09/04/2025 22:30
Onsite Hours : 9:00

ASEC Report ID : 85920
Name of the Project : Ramp 21 Replacement
Project Location : HJAlA
Weather : Clear
Departure Time : 09/05/2025 07:30
ASEC Technician Name : Austin Coleman

PROCTOR DATA SUMMARY

TEST DATE	PROCTOR ID	MAX DRY DENSITY (pcf)	OPTIMUM MOISTURE (%)	PROCTOR TYPE	SOIL DESCRIPTION
	Proctor #1	134.9	8.7	Modified	GAB