


Date : 10/17/2024
Project No : 2024C202
Client Company : CCG
Arrival Time : 10/17/2024 15:00
Onsite Hours : 02:00

ASEC Report ID : 71707
Name of the Project : Old Griffin Rd - Hawthorne Reserve
Project Location : Dallas
Weather : sunny
Departure Time : 10/17/2024 17:00
ASEC Technician Name : Vamsi Polisetty

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

- Upon arrival, the contractor was engaged in cut/fill operations using a CAT 349E for the Lots #86, 87, 88 and 89. Fill was being transported with tandem dump trucks CAT 745 and fill placement was performed using a Komatsu 512PXi. Compaction work was carried out using a CAT 815F.
- As there are no proctor results available yet a proof-roll of this area was performed. Proof-roll observations showed no severe pumping and/or rutting of this area.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you



Date : 10/17/2024
Project No : 2024C202
Client Company : CCG
Arrival Time : 10/17/2024 15:00
Onsite Hours : 02:00

ASEC Report ID : 71707
Name of the Project : Old Griffin Rd - Hawthorne Reserve
Project Location : Dallas
Weather : sunny
Departure Time : 10/17/2024 17:00
ASEC Technician Name : Vamsi Polisetty



Date : 10/17/2024
Project No : 2024C202
Client Company : CCG
Arrival Time : 10/17/2024 15:00
Onsite Hours : 02:00

ASEC Report ID : 71707
Name of the Project : Old Griffin Rd - Hawthorne Reserve
Project Location : Dallas
Weather : sunny
Departure Time : 10/17/2024 17:00
ASEC Technician Name : Vamsi Polisetty



Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.