

Date : 01/27/2025  
Project No : 2024C202  
Client Company : CCG  
Arrival Time : 01/27/2025 07:30  
Onsite Hours : 01:30

ASEC Report ID : 76506  
Name of the Project : Old Griffin Rd - Hawthorne Reserve  
Project Location : Dallas  
Weather : Cloudy and drizzle  
Departure Time : 01/27/2025 09:00  
ASEC Technician Name :

---

Our AS Engineering & Consulting (ASEC) representative arrived on site to observe field activities. The following tasks were performed:

Upon arrival, our representative found the site to be muddy and wet overall with an additional 1 inch of rain falling later. After consultation with the contractor, it was decided that grading operations would be terminated for the day.

Please contact us if you have any questions regarding this report.



Picture depicting muddy with patches of water

*Kenneth Mosman*

**Kenneth Mosman**

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.