

Date : 02/05/2025  
Project No : 2024C202  
Client Company : CCG  
Arrival Time : 02/05/2025 10:00  
Onsite Hours : 07:00

ASEC Report ID : 77021  
Name of the Project : Old Griffin Rd - Hawthorne Reserve  
Project Location : Dallas  
Weather : Partly cloudy  
Departure Time : 02/05/2025 17:00  
ASEC Technician Name : Solomon Cherie

---

## Observations

The above mentioned AS Engineering & Consulting (ASEC) representative arrived on-site to observe field activities. The following tasks were performed:

### Earthwork Activities

The **cut and backfill** activities proceeded throughout the day under favorable weather conditions. The cut was performed using a **349E CAT Excavator**, sourcing material from a nearby cut location. Routine hauling was carried out by **two heavy-duty 745C Loading trucks**.

### Backfilling and Compaction

Backfilling operations continued on **Lots #26 through #30 (backside)**, a process initiated last Monday. A **61Pxi Komatsu Bulldozer** was used for backfilling, and **compaction** was performed with an **815F CAT Roller**.


**Density test results** confirmed that compaction met job specifications for **95% compaction of a standard proctor**. Additionally, **proof-rolling and general probing** verified the stability of these areas.

### Utility Backfilling

The **sewer lines between Manholes E2 & E3** were **backfilled today**. **Density test results** again met the required **95% compaction of a standard proctor**, and stability was confirmed through **proof-rolling and general probing**.



Picture depicting backfilled area at Lots 26-30



Sewer Line backfilled and compacted between Manholes E2 and E3

Date : 02/05/2025  
Project No : 2024C202  
Client Company : CCG  
Arrival Time : 02/05/2025 10:00  
Onsite Hours : 07:00

ASEC Report ID : 77021  
Name of the Project : Old Griffin Rd - Hawthorne Reserve  
Project Location : Dallas  
Weather : Partly cloudy  
Departure Time : 02/05/2025 17:00  
ASEC Technician Name : Solomon Cherie



**Ramchandra R. Mogulla**  
**GA P.E. 036021**  
**Senior Engineer**

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.