

Date : 04/04/2025
Project No : 2024C213
Client Company : WDG
Arrival Time : 04/04/2025 7:30
Onsite Hours : 07:00

ASEC Report ID : 80133
Name of the Project : Covington Town Center PH II
Project Location : Covington, GA
Weather : cloudy
Departure Time : 04/04/2025 14:30
ASEC Technician Name : Aminullah Azimi

As requested, a representative from AS Engineering and Consulting (ASEC) visited the project site to perform quality control inspection and testing services. Visual observation methods were utilized to assess compliance with the project drawings and specifications, applicable codes, and approved material submittals.

Observations Noted on Site:


- Construction activity was ongoing along the stormwater trench extending from MHA0 to MHA1 and MHA2.
- The contractor was installing 18-inch stormwater piping and placing No. #57 stone around the pipe.
- Drilling operations for the stormwater trench between MHA0 and MHB1 were also in progress and continued throughout the day.
- At the time of the visit, the site was not prepared for density testing.

We appreciate the opportunity to provide our services on this project. If you have any questions regarding this report, please feel free to contact us. We would be happy to discuss any aspect of the findings with you



Date : 04/04/2025
Project No : 2024C213
Client Company : WDG
Arrival Time : 04/04/2025 7:30
Onsite Hours : 07:00

ASEC Report ID : 80133
Name of the Project : Covington Town Center PH II
Project Location : Covington, GA
Weather : cloudy
Departure Time : 04/04/2025 14:30
ASEC Technician Name : Aminullah Azimi



Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.