

Date : 04/01/2025  
Project No : 2024C213  
Client Company : WDG  
Arrival Time : 04/01/2025 01:00  
Onsite Hours : 04:00

ASEC Report ID : 79369  
Name of the Project : Covington Town Center PH II  
Project Location : Covington, GA  
Weather : Sunny  
Departure Time : 04/01/2025 05:00  
ASEC Technician Name : Sean Willett

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.


On this date, our ASEC representative was on site as requested by the contractor (Buck Vinson). The technician observed the blasting of residual hard rock for the installation of 18 inches of the HDPE storm line between the structures A-0 and A-1. The contractor began the excavation of loose blast materials from the trench. At this time, no testing was conducted, and all procedures appeared to be performed to job specifications.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Date : 04/01/2025  
Project No : 2024C213  
Client Company : WDG  
Arrival Time : 04/01/2025 01:00  
Onsite Hours : 04:00

ASEC Report ID : 79369  
Name of the Project : Covington Town Center PH II  
Project Location : Covington, GA  
Weather : Sunny  
Departure Time : 04/01/2025 05:00  
ASEC Technician Name : Sean Willett



Date : 04/01/2025  
Project No : 2024C213  
Client Company : WDG  
Arrival Time : 04/01/2025 01:00  
Onsite Hours : 04:00

ASEC Report ID : 79369  
Name of the Project : Covington Town Center PH II  
Project Location : Covington, GA  
Weather : Sunny  
Departure Time : 04/01/2025 05:00  
ASEC Technician Name : Sean Willett

---



**Kenneth Mosman**

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.