

Date : 12/18/2024
Project No : 2024C217
Client Company : Artisan
Arrival Time : 12/18/2024 08:00
Onsite Hours : 08:00

ASEC Report ID : 74612
Name of the Project : Naturewalk - 7 Hills Amenities
Project Location : Dallas
Weather : cloudy
Departure Time : 12/18/2024 16:00
ASEC Technician Name : Vamsi Polisetty

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

Seven Hills: Amenities:

Due to the excessive rainfall in the preceding days, the jobsite remained saturated with excessive moisture. Scarifying and aeration of surficial soils continued this week.

Savannah Pipeline Company has continued the installation of stormwater lines at the amenities job site, located between the clubhouse and tennis court area. Excavation work is being carried out using the Kobelco SK350LC excavator. Compaction efforts are being executed with a Hamm Shep Toe compactor and a remote-controlled compactor.

- Compaction testing was performed using a Troxler nuclear density gauge, along with general probing using a 3/8" diameter probe rod.
- Density test results indicate that compacted materials did meet the project requirement of 95% of the maximum dry density obtained by a Standard Proctor ASTM 698.

Nature Walk: Lot #995

Lot #995 grade work continued using a Komatsu 39PXI dozer and a Komatsu PC240LC excavator. No backfilling was done except for the slopes.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Date : 12/18/2024
Project No : 2024C217
Client Company : Artisan
Arrival Time : 12/18/2024 08:00
Onsite Hours : 08:00

ASEC Report ID : 74612
Name of the Project : Naturewalk - 7 Hills Amenities
Project Location : Dallas
Weather : cloudy
Departure Time : 12/18/2024 16:00
ASEC Technician Name : Vamsi Polisetty



Date : 12/18/2024
Project No : 2024C217
Client Company : Artisan
Arrival Time : 12/18/2024 08:00
Onsite Hours : 08:00

ASEC Report ID : 74612
Name of the Project : Naturewalk - 7 Hills Amenities
Project Location : Dallas
Weather : cloudy
Departure Time : 12/18/2024 16:00
ASEC Technician Name : Vamsi Polisetty



Date : 12/18/2024
Project No : 2024C217
Client Company : Artisan
Arrival Time : 12/18/2024 08:00
Onsite Hours : 08:00

ASEC Report ID : 74612
Name of the Project : Naturewalk - 7 Hills Amenities
Project Location : Dallas
Weather : cloudy
Departure Time : 12/18/2024 16:00
ASEC Technician Name : Vamsi Polisetty




Date : 12/18/2024
Project No : 2024C217
Client Company : Artisan
Arrival Time : 12/18/2024 08:00
Onsite Hours : 08:00

ASEC Report ID : 74612
Name of the Project : Naturewalk - 7 Hills Amenities
Project Location : Dallas
Weather : cloudy
Departure Time : 12/18/2024 16:00
ASEC Technician Name : Vamsi Polisetty



Date : 12/18/2024
Project No : 2024C217
Client Company : Artisan
Arrival Time : 12/18/2024 08:00
Onsite Hours : 08:00

ASEC Report ID : 74612
Name of the Project : Naturewalk - 7 Hills Amenities
Project Location : Dallas
Weather : cloudy
Departure Time : 12/18/2024 16:00
ASEC Technician Name : Vamsi Polisetty



Date : 12/18/2024
Project No : 2024C217
Client Company : Artisan
Arrival Time : 12/18/2024 08:00
Onsite Hours : 08:00

ASEC Report ID : 74612
Name of the Project : Naturewalk - 7 Hills Amenities
Project Location : Dallas
Weather : cloudy
Departure Time : 12/18/2024 16:00
ASEC Technician Name : Vamsi Polisetty



Date : 12/18/2024
Project No : 2024C217
Client Company : Artisan
Arrival Time : 12/18/2024 08:00
Onsite Hours : 08:00

ASEC Report ID : 74612
Name of the Project : Naturewalk - 7 Hills Amenities
Project Location : Dallas
Weather : cloudy
Departure Time : 12/18/2024 16:00
ASEC Technician Name : Vamsi Polisetty



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.