

Date : 12/24/2024
Project No : 2024C217
Client Company : Artisan
Arrival Time : 12/24/2024 08:00
Onsite Hours : 08:00

ASEC Report ID : 74919
Name of the Project : Naturewalk - 7 Hills Amenities
Project Location : Dallas
Weather : sunny
Departure Time : 12/24/2024 16:00
ASEC Technician Name : Vamsi Polisetty

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

Nature Walk: Lot #995:

No backfilling has been conducted on this lot today. The section near Lot #995, as well as the vicinity around the roundabout, has been dozed using a Komatsu D39PXI bulldozer. This preparation is part of sealing up the site for protection against inclement weather for the upcoming holidays.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Date : 12/24/2024
Project No : 2024C217
Client Company : Artisan
Arrival Time : 12/24/2024 08:00
Onsite Hours : 08:00

ASEC Report ID : 74919
Name of the Project : Naturewalk - 7 Hills Amenities
Project Location : Dallas
Weather : sunny
Departure Time : 12/24/2024 16:00
ASEC Technician Name : Vamsi Polisetty



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.