

Date : 11/27/2024
Project No : 2024C217
Client Company : Artisan
Arrival Time : 11/27/2024 08:30
Onsite Hours : 08:30

ASEC Report ID : 74108
Name of the Project : Naturewalk - 7 Hills Amenities
Project Location : Dallas
Weather : cloudy
Departure Time : 11/27/2024 17:00
ASEC Technician Name : Vamsi Polisetty

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

Seven Hills: Amenities

- Upon arrival, the contractor was engaged in grade work for the roadway using a Komatsu PC 360LC and cutting from the west of the job site. Fill was being transported with two tandem-axled dump trucks for the tennis court and parking area, while dozing was performed with a Komatsu 39px and compaction with CAT563E.
- Proof-rolling of the boulder fill was utilized to verify stability in lieu of density testing using a nuclear density gauge.

Nature walk: Lot Inspection (Lot #1000, #1001, #1002, #1003, #1004, #1005 and #1006).

- The contractor utilized a Komatsu D85EX bulldozer to perform the cutting of the slopes.
- In addition, a Komatsu PC210 LC excavator was employed for the breaking up of on-site boulders. Equipped with a hydraulic hammer, the excavator was used to break large rocks and boulders encountered on the site.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Date : 11/27/2024
Project No : 2024C217
Client Company : Artisan
Arrival Time : 11/27/2024 08:30
Onsite Hours : 08:30

ASEC Report ID : 74108
Name of the Project : Naturewalk - 7 Hills Amenities
Project Location : Dallas
Weather : cloudy
Departure Time : 11/27/2024 17:00
ASEC Technician Name : Vamsi Polisetty



Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.