

Date : 12/12/2024  
Project No : 2024C217  
Client Company : Artisan  
Arrival Time : 12/12/2024 08:00  
Onsite Hours : 08:00

ASEC Report ID : 74287  
Name of the Project : Naturewalk - 7 Hills Amenities  
Project Location : Dallas  
Weather : sunny  
Departure Time : 12/12/2024 16:00  
ASEC Technician Name : Vamsi Polisetty

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

**Seven Hills: Amenities**

Due to the rainfall from the previous days, the job site remained saturated with excessive moisture. To address this, the contractor began scarifying and aerating surficial soils using various dozer equipment. The site will be allowed to aerate throughout the day in anticipation of beginning grade work again tomorrow.

Savannah Pipeline Company has initiated the installation of stormwater lines at the amenities job site, located between the clubhouse and tennis court area. Excavation work was being carried out using the Kobelco SK350LC excavator. Compaction efforts are being executed with a Hamm Shoe Toe compactor and a remote-controlled compactor.

For the day's progress, the installation of manholes A1, A2, A2A, and A3 has been successfully completed.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Date : 12/12/2024  
Project No : 2024C217  
Client Company : Artisan  
Arrival Time : 12/12/2024 08:00  
Onsite Hours : 08:00

ASEC Report ID : 74287  
Name of the Project : Naturewalk - 7 Hills Amenities  
Project Location : Dallas  
Weather : sunny  
Departure Time : 12/12/2024 16:00  
ASEC Technician Name : Vamsi Polisetty




Date : 12/12/2024  
Project No : 2024C217  
Client Company : Artisan  
Arrival Time : 12/12/2024 08:00  
Onsite Hours : 08:00

ASEC Report ID : 74287  
Name of the Project : Naturewalk - 7 Hills Amenities  
Project Location : Dallas  
Weather : sunny  
Departure Time : 12/12/2024 16:00  
ASEC Technician Name : Vamsi Polisetty



Date : 12/12/2024  
Project No : 2024C217  
Client Company : Artisan  
Arrival Time : 12/12/2024 08:00  
Onsite Hours : 08:00

ASEC Report ID : 74287  
Name of the Project : Naturewalk - 7 Hills Amenities  
Project Location : Dallas  
Weather : sunny  
Departure Time : 12/12/2024 16:00  
ASEC Technician Name : Vamsi Polisetty



Date : 12/12/2024  
Project No : 2024C217  
Client Company : Artisan  
Arrival Time : 12/12/2024 08:00  
Onsite Hours : 08:00

ASEC Report ID : 74287  
Name of the Project : Naturewalk - 7 Hills Amenities  
Project Location : Dallas  
Weather : sunny  
Departure Time : 12/12/2024 16:00  
ASEC Technician Name : Vamsi Polisetty



Date : 12/12/2024  
Project No : 2024C217  
Client Company : Artisan  
Arrival Time : 12/12/2024 08:00  
Onsite Hours : 08:00

ASEC Report ID : 74287  
Name of the Project : Naturewalk - 7 Hills Amenities  
Project Location : Dallas  
Weather : sunny  
Departure Time : 12/12/2024 16:00  
ASEC Technician Name : Vamsi Polisetty



Date : 12/12/2024  
Project No : 2024C217  
Client Company : Artisan  
Arrival Time : 12/12/2024 08:00  
Onsite Hours : 08:00

ASEC Report ID : 74287  
Name of the Project : Naturewalk - 7 Hills Amenities  
Project Location : Dallas  
Weather : sunny  
Departure Time : 12/12/2024 16:00  
ASEC Technician Name : Vamsi Polisetty



Date : 12/12/2024  
Project No : 2024C217  
Client Company : Artisan  
Arrival Time : 12/12/2024 08:00  
Onsite Hours : 08:00

ASEC Report ID : 74287  
Name of the Project : Naturewalk - 7 Hills Amenities  
Project Location : Dallas  
Weather : sunny  
Departure Time : 12/12/2024 16:00  
ASEC Technician Name : Vamsi Polisetty



**Kenneth Mosman**

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.