

Date : 09/25/2024
Project No : 2024C217
Client Company : Artisan
Arrival Time : 09/25/2024 09:00
Onsite Hours : 08:00

ASEC Report ID : 70994
Name of the Project : Naturewalk - 7 Hills Amenities
Project Location : Dallas
Weather : Rainy
Departure Time : 09/25/2024 17:00
ASEC Technician Name :

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

- Upon arrival, our representative found the weather to be rainy with the contractor engaged in excavating using a Komatsu PC 360LC in the west of the project site. Soils were being transported with tandem-axled dump trucks, while dozing was performed with a Komatsu D85EX.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.