

Date : 09/30/2024  
Project No : 2024C217  
Client Company : Artisan  
Arrival Time : 09/30/2024 08:00  
Onsite Hours : 9:00

ASEC Report ID : 70996  
Name of the Project : Naturewalk - 7 Hills Amenities  
Project Location : Dallas  
Weather : Cloudy  
Departure Time : 09/30/2024 17:00  
ASEC Technician Name : Vamsi Polisetty

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

- Upon arrival, the contractor was actively engaged in excavating using a Komatsu PC 360LC. They were also performing dozing operations with Komatsu 39PX. The entire site was being scarified and aerated to dry out from the recent rains and excess moisture contents.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Date : 09/30/2024  
Project No : 2024C217  
Client Company : Artisan  
Arrival Time : 09/30/2024 08:00  
Onsite Hours : 9:00

ASEC Report ID : 70996  
Name of the Project : Naturewalk - 7 Hills Amenities  
Project Location : Dallas  
Weather : Cloudy  
Departure Time : 09/30/2024 17:00  
ASEC Technician Name : Vamsi Polisetty



*Kenneth Mosman*

**Kenneth Mosman**

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.