

Date : 04/29/2025
Project No : 2024C217
Client Company : Artisan
Arrival Time : 04/29/2025 08:00
Onsite Hours : 04:00

ASEC Report ID : 81093
Name of the Project : Naturewalk - 7 Hills Amenities
Project Location : Dallas
Weather : cloudy
Departure Time : 04/29/2025 12:00
ASEC Technician Name : Clyde Smith

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

Our ASEC representative was on site as requested to observe slope failure repairs for Lots #975-3982. Following a period of stand-by time, the contractor did not show at the job site and work was cancelled for the day.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Date : 04/29/2025
Project No : 2024C217
Client Company : Artisan
Arrival Time : 04/29/2025 08:00
Onsite Hours : 04:00

ASEC Report ID : 81093
Name of the Project : Naturewalk - 7 Hills Amenities
Project Location : Dallas
Weather : cloudy
Departure Time : 04/29/2025 12:00
ASEC Technician Name : Clyde Smith



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.