

Date : 07/11/2025  
Project No : 2024C217  
Client Company : Artisan  
Arrival Time : 07/11/2025 9:00  
Onsite Hours : 08:00

ASEC Report ID : 83440  
Name of the Project : Naturewalk - 7 Hills Amenities  
Project Location : Dallas  
Weather : sunny  
Departure Time : 07/11/2025 17:00  
ASEC Technician Name : Aminullah Azimi

As requested, a representative from AS Engineering and Consulting (ASEC) visited the site to perform quality control inspection and testing services. Visual observation techniques were employed to verify compliance with the project drawings, specifications, applicable codes, and approved material submittals.

During the site visit, the contractor had prepared the slope area located to the east of Lot #92 by removing all grass, organic material, and roots prior to fill placement. Due to elevation differences, some areas were too high for the dozer to access; these areas were manually cleaned by laborers using shovels. Once the surface was properly prepared, imported soil from an external source was delivered to the site, evenly spread across the area, and compacted using a dozer. To support erosion control and landscaping, the contractor applied a mix of Bermuda grass and fescue grass seeds, followed by the installation of a straw blanket. An all-purpose fertilizer was also applied to promote healthy vegetation growth across the treated area.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Date : 07/11/2025  
Project No : 2024C217  
Client Company : Artisan  
Arrival Time : 07/11/2025 9:00  
Onsite Hours : 08:00

ASEC Report ID : 83440  
Name of the Project : Naturewalk - 7 Hills Amenities  
Project Location : Dallas  
Weather : sunny  
Departure Time : 07/11/2025 17:00  
ASEC Technician Name : Aminullah Azimi



Date : 07/11/2025  
Project No : 2024C217  
Client Company : Artisan  
Arrival Time : 07/11/2025 9:00  
Onsite Hours : 08:00

ASEC Report ID : 83440  
Name of the Project : Naturewalk - 7 Hills Amenities  
Project Location : Dallas  
Weather : sunny  
Departure Time : 07/11/2025 17:00  
ASEC Technician Name : Aminullah Azimi




Date : 07/11/2025  
Project No : 2024C217  
Client Company : Artisan  
Arrival Time : 07/11/2025 9:00  
Onsite Hours : 08:00

ASEC Report ID : 83440  
Name of the Project : Naturewalk - 7 Hills Amenities  
Project Location : Dallas  
Weather : sunny  
Departure Time : 07/11/2025 17:00  
ASEC Technician Name : Aminullah Azimi



Date : 07/11/2025  
Project No : 2024C217  
Client Company : Artisan  
Arrival Time : 07/11/2025 9:00  
Onsite Hours : 08:00

ASEC Report ID : 83440  
Name of the Project : Naturewalk - 7 Hills Amenities  
Project Location : Dallas  
Weather : sunny  
Departure Time : 07/11/2025 17:00  
ASEC Technician Name : Aminullah Azimi



Date : 07/11/2025  
Project No : 2024C217  
Client Company : Artisan  
Arrival Time : 07/11/2025 9:00  
Onsite Hours : 08:00

ASEC Report ID : 83440  
Name of the Project : Naturewalk - 7 Hills Amenities  
Project Location : Dallas  
Weather : sunny  
Departure Time : 07/11/2025 17:00  
ASEC Technician Name : Aminullah Azimi



*Kenneth Mosman*

**Kenneth Mosman**

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.