

Date : 07/16/2025  
Project No : 2024C217  
Client Company : Artisan  
Arrival Time : 07/16/2025 9:30  
Onsite Hours : 03:30

ASEC Report ID : 83552  
Name of the Project : Naturewalk - 7 Hills Amenities  
Project Location : Dallas  
Weather : sunny  
Departure Time : 07/16/2025 13:00  
ASEC Technician Name : Aminullah Azimi

As requested, a representative from AS Engineering and Consulting (ASEC) visited the site to perform quality control inspection and testing services. Visual observation techniques were used to verify compliance with the project drawings, specifications, applicable codes, and approved material submittals.

During the site visit, the contractor mortared the pipes into the drainage box and tied in the gutter downspouts to the box. Hydroseeding was also performed using a mix of lovegrass, clover, and fescue. Additionally, hand compactors were used to compact the soil around the house.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Date : 07/16/2025  
Project No : 2024C217  
Client Company : Artisan  
Arrival Time : 07/16/2025 9:30  
Onsite Hours : 03:30

ASEC Report ID : 83552  
Name of the Project : Naturewalk - 7 Hills Amenities  
Project Location : Dallas  
Weather : sunny  
Departure Time : 07/16/2025 13:00  
ASEC Technician Name : Aminullah Azimi



Date : 07/16/2025  
Project No : 2024C217  
Client Company : Artisan  
Arrival Time : 07/16/2025 9:30  
Onsite Hours : 03:30

ASEC Report ID : 83552  
Name of the Project : Naturewalk - 7 Hills Amenities  
Project Location : Dallas  
Weather : sunny  
Departure Time : 07/16/2025 13:00  
ASEC Technician Name : Aminullah Azimi



*Kenneth Mosman*

**Kenneth Mosman**

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.