

Date : 06/20/2025
Project No : 2024C217
Client Company : Artisan
Arrival Time : 06/20/2025 11:00
Onsite Hours : 05:30

ASEC Report ID : 82763
Name of the Project : Naturewalk - 7 Hills Amenities
Project Location : Dallas
Weather : sunny
Departure Time : 06/20/2025 16:30
ASEC Technician Name : Aminullah Azimi

As requested, our AS Engineering and Consulting (ASEC) representative visited the site to provide quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawings and specifications, applicable codes, and approved material submittals. The following observations were made on site during this visit:

Work was in progress on the water line at the entrance, as well as in the parking lots and on the slope. No testing was performed on this day. One crew was excavating the water line trench and drilling through rock, while a second crew was leveling the parking lots and continuing work on the slope.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We would be happy to discuss it with you.



Date : 06/20/2025
Project No : 2024C217
Client Company : Artisan
Arrival Time : 06/20/2025 11:00
Onsite Hours : 05:30

ASEC Report ID : 82763
Name of the Project : Naturewalk - 7 Hills Amenities
Project Location : Dallas
Weather : sunny
Departure Time : 06/20/2025 16:30
ASEC Technician Name : Aminullah Azimi



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.