

Date : 07/17/2025
Project No : 2024C217
Client Company : Artisan
Arrival Time : 07/17/2025 15:00
Onsite Hours : 01:00

ASEC Report ID : 83566
Name of the Project : Naturewalk - 7 Hills Amenities
Project Location : Dallas
Weather : sunny
Departure Time : 07/17/2025 16:00
ASEC Technician Name : Aminullah Azimi

As requested, a representative from AS Engineering and Consulting (ASEC) visited the site to perform quality control inspection and testing services. Visual observation techniques were used to verify compliance with the project drawings, specifications, applicable codes, and approved material submittals.

During the site visit, new Bermuda grass was installed around the house as well as in areas where machinery had been operating to restore disturbed ground. Additionally, hydroseeding was performed using a mix of lovegrass, clover, and fescue to promote vegetation growth and long-term site stabilization.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Date : 07/17/2025
Project No : 2024C217
Client Company : Artisan
Arrival Time : 07/17/2025 15:00
Onsite Hours : 01:00

ASEC Report ID : 83566
Name of the Project : Naturewalk - 7 Hills Amenities
Project Location : Dallas
Weather : sunny
Departure Time : 07/17/2025 16:00
ASEC Technician Name : Aminullah Azimi



Date : 07/17/2025
Project No : 2024C217
Client Company : Artisan
Arrival Time : 07/17/2025 15:00
Onsite Hours : 01:00

ASEC Report ID : 83566
Name of the Project : Naturewalk - 7 Hills Amenities
Project Location : Dallas
Weather : sunny
Departure Time : 07/17/2025 16:00
ASEC Technician Name : Aminullah Azimi



Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.