

Date : 07/22/2025  
Project No : 2024C217  
Client Company : Artisan  
Arrival Time : 07/22/2025 09:00  
Onsite Hours : 04:00

ASEC Report ID : 83330  
Name of the Project : Naturewalk - 7 Hills Amenities  
Project Location : Dallas  
Weather : Mostly Cloudy  
Departure Time : 07/22/2025 13:00  
ASEC Technician Name : Safiullah Momand


As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

Due to overnight rainfall, most areas designated for work were saturated, preventing any progress on the project site. As a result, all activities were postponed for the day.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Rain disturbed the existing GAB



Rain disturbed the surface



Rain disturbed the existing GAB



Rain disturbed the existing GAB

Date : 07/22/2025  
Project No : 2024C217  
Client Company : Artisan  
Arrival Time : 07/22/2025 09:00  
Onsite Hours : 04:00

ASEC Report ID : 83330  
Name of the Project : Naturewalk - 7 Hills Amenities  
Project Location : Dallas  
Weather : Mostly Cloudy  
Departure Time : 07/22/2025 13:00  
ASEC Technician Name : Safiullah Momand



Rain disturbed the existing GAB



Rain disturbed the Subgrade surface

*Kenneth Mosman*

**Kenneth Mosman**

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.