

Date : 07/25/2025  
Project No : 2024C217  
Client Company : Artisan  
Arrival Time : 07/25/2025 07:30  
Onsite Hours : 02:30

ASEC Report ID : 83369  
Name of the Project : Naturewalk - 7 Hills Amenities  
Project Location : Dallas  
Weather : Sunny  
Departure Time : 07/25/2025 10:00  
ASEC Technician Name : Clyde Smith

---

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

Our ASEC representative visited the above site and met with grading contractor and blasting contractor to arrange scheduling for on-site technicians. The grading contractor stated approximately ten feet of fill had been placed at the roadway embankment. A technician was scheduled to remain on site and observe fill placement while performing density testing.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



**Kenneth Mosman**

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.