

Date : 11/21/2024
Project No : 2024C297
Client Company : Artisan
Arrival Time : 11/21/2024 08:00
Onsite Hours : 08:00

ASEC Report ID : 74078
Name of the Project : Nature Walk - Footing Inspections
Project Location : Dallas
Weather : sunny
Departure Time : 11/21/2024 16:00
ASEC Technician Name : Vamsi Polisetty

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

Nature walk: Footings Inspection (Lot #1007)

- A Dynamic Cone Penetrometer (DCP) test was performed on all four sides of Lot #1007, revealing the presence of small stones and rocks, which resulted in auger refusal at relatively different depths.
 - **West Side:** Auger refusal was encountered at a depth of 3 feet, with 7 blows at 1 foot and 6 blows at 2 feet. Refusal was followed by an offset at 2 feet, requiring 13 blows at 1 foot.
 - **South Side:** Auger refusal was encountered at a depth of 3 feet, with 7 blows at 1 foot and 5 blows at 2 feet. Refusal was followed by an offset at 2 feet, requiring 5 blows at 1 foot.
 - **East Side:** Auger refusal was encountered at a depth of 4 feet, with 3 blows at 1 foot, 5 blows at 2 feet, and 14 blows at 3 feet.
 - **North Side:** Auger refusal was encountered at a depth of 2 feet, with 6 blows at 1 foot. Refusal was followed by an offset at 2 feet, requiring 9 blows at 1 foot.

These results indicate varying depths of auger refusal across the site, reflecting different subsurface conditions.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you



Date : 11/21/2024
Project No : 2024C297
Client Company : Artisan
Arrival Time : 11/21/2024 08:00
Onsite Hours : 08:00

ASEC Report ID : 74078
Name of the Project : Nature Walk - Footing Inspections
Project Location : Dallas
Weather : sunny
Departure Time : 11/21/2024 16:00
ASEC Technician Name : Vamsi Polisetty



Date : 11/21/2024
Project No : 2024C297
Client Company : Artisan
Arrival Time : 11/21/2024 08:00
Onsite Hours : 08:00

ASEC Report ID : 74078
Name of the Project : Nature Walk - Footing Inspections
Project Location : Dallas
Weather : sunny
Departure Time : 11/21/2024 16:00
ASEC Technician Name : Vamsi Polisetty



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.