

Date : 02/05/2025  
Project No : 2024C315  
Client Company : J. Chapman Const.  
Arrival Time : 02/05/2025 09:00  
Onsite Hours : 07:00

ASEC Report ID : 77231  
Name of the Project : Cottages at Villa Rica - Rock Blasting  
Project Location : Villa Rica  
Weather : Cloudy  
Departure Time : 02/05/2025 16:00  
ASEC Technician Name : Micah Aycock

The aforementioned AS Engineering and Consulting (ASEC) representative visited the Cottages at Villa Rica site to monitor drilling and rock removal operations. The contractor performing the work was Precision Blasting. The following observations were made on-site:

**Drilling Data:**

There were no blasts today so the team continued drilling west along the same trench pattern where they left off previously. The drilling continued just north of lot #132 while one driller drilled the lateral for lot #132. The team ended the day with drilling a trench pattern southwest of lot #132 heading towards lot #191 and #192.

We appreciate the opportunity to assist you with this project. Should you have any questions regarding this report, please do not hesitate to contact us. We would be happy to discuss it with you.



**Ramchandra R. Mogulla**  
**GA P.E. 036021**  
**Senior Engineer**

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.