

Date : 02/27/2025
Project No : 2024C315
Client Company : J. Chapman Const.
Arrival Time : 02/27/2025 12:00
Onsite Hours : 02:00

ASEC Report ID : 78436
Name of the Project : Cottages at Villa Rica - Rock Blasting
Project Location : Villa Rica
Weather : overcast
Departure Time : 02/27/2025 14:00
ASEC Technician Name : Micah Aycock

Site Visit Report - Cottages at Villa Rica

An AS Engineering and Consulting (ASEC) representative visited the Cottages at Villa Rica site to monitor drilling and rock removal operations. The contractor performing the work was Precision Blasting. The following observations were made on-site:

Site Observations:

No drilling or blasting activities took place today. Precision Blasting informed us that they were waiting for surveyors to complete the mapping of the next drilling location, which was expected to occur later in the afternoon.

The site visit, including travel time, accounted for two hours.

We appreciate the opportunity to assist with this project. If you have any questions regarding this report, please do not hesitate to contact us. We would be happy to discuss any details further.



Ramchandra R. Mogulla
GA P.E. 036021
Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.