

Date : 03/11/2025  
Project No : 2024C315  
Client Company : J. Chapman Const.  
Arrival Time : 03/11/2025 10:00  
Onsite Hours : 07:30

ASEC Report ID : 78680  
Name of the Project : Cottages at Villa Rica - Rock Blasting  
Project Location : Villa Rica  
Weather : Sunny  
Departure Time : 03/11/2025 17:30  
ASEC Technician Name : Micah Aycock

---

**Site Visit Report - Cottages at Villa Rica**

An AS Engineering and Consulting (ASEC) representative visited the Cottages at Villa Rica site to monitor drilling and rock removal operations. The contractor performing the work was Precision Blasting. The following observations were made on-site:

**Drilling Data:**

Today, the drilling team continued working on the mass rock pattern in the northeast corner of the development. Drilling began at Lot #57 and progressed south toward Lot #58. The hole spacing remained consistent at 6 feet throughout the operation.

We appreciate the opportunity to assist with this project. If you have any questions regarding this report, please do not hesitate to contact us. We would be happy to discuss any details further.



**Ramchandra R. Mogulla**  
GA P.E. 036021  
Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.