

Date : 03/06/2025  
Project No : 2024C315  
Client Company : J. Chapman Const.  
Arrival Time : 03/06/2025 10:00  
Onsite Hours : 06:00

ASEC Report ID : 78675  
Name of the Project : Cottages at Villa Rica - Rock Blasting  
Project Location : Villa Rica  
Weather : Sunny  
Departure Time : 03/06/2025 16:00  
ASEC Technician Name : Micah Aycock

---

**Site Visit Report - Cottages at Villa Rica**

An AS Engineering and Consulting (ASEC) representative visited the Cottages at Villa Rica site to monitor drilling and rock removal operations. The contractor performing the work was Precision Blasting.

**Drilling Data:**

Today's drilling operations continued in the northeast corner of the development, between Lot #53 and Lot #54. The drilling followed a mass rock pattern with hole spacing of 6 feet.

We appreciate the opportunity to assist with this project. If you have any questions regarding this report, please do not hesitate to contact us. We would be happy to discuss any details further



Lot #53



Date : 03/06/2025  
Project No : 2024C315  
Client Company : J. Chapman Const.  
Arrival Time : 03/06/2025 10:00  
Onsite Hours : 06:00

ASEC Report ID : 78675  
Name of the Project : Cottages at Villa Rica - Rock Blasting  
Project Location : Villa Rica  
Weather : Sunny  
Departure Time : 03/06/2025 16:00  
ASEC Technician Name : Micah Aycock



**Ramchandra R. Mogulla**  
**GA P.E. 036021**  
**Senior Engineer**

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.