

Date : 02/28/2025  
Project No : 2024C315  
Client Company : J. Chapman Const.  
Arrival Time : 02/28/2025 12:00  
Onsite Hours : 02:00

ASEC Report ID : 78438  
Name of the Project : Cottages at Villa Rica - Rock Blasting  
Project Location : Villa Rica  
Weather : Sunny  
Departure Time : 02/28/2025 14:00  
ASEC Technician Name : Micah Aycock

---

### Site Visit Report - Cottages at Villa Rica

An AS Engineering and Consulting (ASEC) representative visited the Cottages at Villa Rica site to monitor drilling and rock removal operations. The contractor performing the work was Precision Blasting.

#### Site Observations:

No drilling or blasting activities took place today. Precision Blasting informed us that they were waiting for surveyors to complete the mapping of the next drilling location, which was expected to occur later in the afternoon.

The reported two hours account for travel time to and from the site.

We appreciate the opportunity to assist with this project. Please feel free to reach out if you have any questions or need further details.



**Ramchandra R. Mogulla**  
GA P.E. 036021  
Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.