

Date : 03/07/2025
Project No : 2024C315
Client Company : J. Chapman Const.
Arrival Time : 03/07/2025 10:00
Onsite Hours : 05:00

ASEC Report ID : 78678
Name of the Project : Cottages at Villa Rica - Rock Blasting
Project Location : Villa Rica
Weather : Sunny
Departure Time : 03/07/2025 15:00
ASEC Technician Name : Micah Aycock

Site Visit Report - Cottages at Villa Rica

An AS Engineering and Consulting (ASEC) representative visited the Cottages at Villa Rica site to monitor drilling and rock removal operations. The contractor performing the work was Precision Blasting. The following observations were made on-site:

Drilling Data:

Today, the drilling team continued working on the mass rock pattern in the northeast corner of the development. Drilling began at Lot #55 and progressed south toward Lot #56. The hole spacing remained consistent at 6 feet throughout the operation.

The attached plan sketch shows the general area drilling was performed.

We appreciate the opportunity to assist with this project. If you have any questions regarding this report, please do not hesitate to contact us. We would be happy to discuss any details further.



Lot #56

Date : 03/07/2025
Project No : 2024C315
Client Company : J. Chapman Const.
Arrival Time : 03/07/2025 10:00
Onsite Hours : 05:00

ASEC Report ID : 78678
Name of the Project : Cottages at Villa Rica - Rock Blasting
Project Location : Villa Rica
Weather : Sunny
Departure Time : 03/07/2025 15:00
ASEC Technician Name : Micah Aycock



Ramchandra R. Mogulla
GA P.E. 036021
Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.