

Date : 03/20/2025
Project No : 2024C315
Client Company : J. Chapman Const.
Arrival Time : 03/20/2025 09:00
Onsite Hours : 07:00

ASEC Report ID : 79120
Name of the Project : Cottages at Villa Rica - Rock Blasting
Project Location : Villa Rica
Weather : overcast
Departure Time : 03/20/2025 16:00
ASEC Technician Name : Micah Aycock

The AS Engineering and Consulting (ASEC) representative visited the Cottages at Villa Rica site to monitor drilling and rock removal operations. The contractor performing the work was Precision Blasting. The following observations were made on-site:

Drilling Data:

Today the drilling operation continued in the northern section of the development. The laterals that were drilled are trench in trench pattern #46, #47, #48, and #127. These drillings are a continuation of yesterday's work in preparation for tomorrow's blasting. We appreciate the opportunity to assist with this project. Should you have any questions regarding this report, please do not hesitate to contact us. We would be happy to discuss any details further.



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.