

Date : 04/17/2025
Project No : 2025C146
Client Company : Davidson Homes, LLC
Arrival Time : 04/17/2025 10:00
Onsite Hours : 05:30

ASEC Report ID : 80046
Name of the Project : Greene Farms Subdivision
Project Location : 1451 Highway 113, Cartersville, Georgia
Weather : Sunny
Departure Time : 04/17/2025 15:30
ASEC Technician Name : Clyde Smith

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

Our ASEC representative was on site as requested and observed the grading contractor continue placing fill for the building pads and roadway. The contractor used soils from an off-site borrow and on site cut areas from the southwest corner of the site. Density tests were performed on Lots #13 and #14 using a Troxler nuclear gauge model 3430, serial no. 38069. Results are attached. Our representative also recommended to the contractor to limit fill lift thicknesses to 8 to 10 inches prior to compacting.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Date : 04/17/2025
Project No : 2025C146
Client Company : Davidson Homes, LLC
Arrival Time : 04/17/2025 10:00
Onsite Hours : 05:30

ASEC Report ID : 80046
Name of the Project : Greene Farms Subdivision
Project Location : 1451 Highway 113, Cartersville, Georgia
Weather : Sunny
Departure Time : 04/17/2025 15:30
ASEC Technician Name : Clyde Smith



Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.