

Date : 04/21/2025
Project No : 2025C149
Client Company : Davidson Homes
Arrival Time : 04/21/2025 08:00
Onsite Hours : 03:00

ASEC Report ID : 80292
Name of the Project : Grove at E. Thompson Mill Rd
Project Location : Buford
Weather : Sunny
Departure Time : 04/21/2025 11:00
ASEC Technician Name : Clyde Smith

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

On the above date our ASEC representative obtained a field proctor at the Atlanta lab that was picked up from on-site on 4/18/25.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.