

Date : 05/01/2025  
Project No : 2025C149  
Client Company : Davidson Homes  
Arrival Time : 05/01/2025 08:45  
Onsite Hours : 01:30

ASEC Report ID : 80933  
Name of the Project : Grove at E. Thompson Mill Rd  
Project Location : Buford  
Weather :  
Departure Time : 05/01/2025 10:15  
ASEC Technician Name : Solomon Cherie

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

Upon arrival, our ASEC representative found the site to be too wet for grading operations today. Contractor elected to pump out ponds this day.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Picture depicting wet dirt and ponds filled water

*Kenneth Mosman*

**Kenneth Mosman**

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.