

Date : 04/24/2025
Project No : 2025C149
Client Company : Davidson Homes
Arrival Time : 04/23/2025 8:00
Onsite Hours : 04:00

ASEC Report ID : 81676
Name of the Project : Grove at E. Thompson Mill Rd
Project Location : Buford
Weather : cloudy
Departure Time : 04/23/2025 12:00
ASEC Technician Name : Aminullah Azimi

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

Our ASEC representative arrived on-site to perform soil compaction and testing. However, due to the saturated soil conditions, density tests could not be performed. Consequently, the contractor has decided to postpone grade work until the site dries out.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.